Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080109-3

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY

No 128103

RECEIVED FROM LIBERTY MFG. CO

DATE REC'D 1-16-57
P. O. NO. 69075
VENDOR PACKING SLIP NO. 10520

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO.
322	000000	10183	C	0	0 0	00	02		

S. O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	73C163-1 [illegible] MTG [illegible] AN 3102A-16S-1P	10	✓	

RECEIVED BY

INSPECTED BY

DATE 1/12/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128104

RECEIVED FROM LIBERTY MFG. CO

DATE REC'D 1-16-57
P. O. NO. 69075
VENDOR PACKING SLIP NO. 10520

CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO.
322	000000	10184	C	0	0 C	00	02		

S. O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
10	73C164-13 [illegible] 90 ° [illegible] CONNECTOR AN 3108-41/3 [illegible]	10	✓	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080109-3

RECEIVED

INSPECTED

DATE 1/12/57

REJECTS RETURNED ON SHIP. MEMO NO.